

14CFR part 141

Safety Summit

“Maintenance”

Presented to: “14CFR part 141 Pilot Schools”

By: Tony Alfaya, Program Manager

Orlando FSDO FAASTeam


Date: May 10, 2018



**Federal Aviation
Administration**



Small crack on forward leading edge top and bottom of bracket.



PA-28R-201 “Arrow”

TTIS: 8570.2




PA-28RT-201 “Arrow”

TTIS: 12186.3




PA-28RT-201 "Arrow"

TTIS: 12186.3




PA-28-161 “Warrior”

TTIS: 12383.4



PA-28-161 “Warrior”

TTIS: 21916.5



PA-28-161 “Warrior”

TTIS: 21916.5



